



BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

No. IR 51322TT-6

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

| CUSTOMER HALLIBURTON ICC | | 3rd PARTY <input type="checkbox"/> | FACILITY / LOCATION TEST TOOLS | AUTHORIZED BY BOBBY CHOATE | | INVOICE NO. | | |
|-----------------------------|--------------|---------------------------------------|-----------------------------------|-------------------------------|---------------------------------|-------------|-------------------|------|
| RIG | | OCS-G & WELL NO. | | PROJECT BP | P.O. NO. / JOB NO. 907695892 | | DATE 5/13/2022 | |
| SERIAL NO. | DESCRIPTION | | PIN | BOX | I.D. | O.D. | LENGTH | |
| 1 | EQ# 10255374 | 8 5/8" - 13 3/8" RTTS SAFETY JOINT | | | | | | |
| 2 | G3536856-2 | TOP COUPLNG - ACC | | | 5 1/4 CAS x INT - ACC | 3 3/4 | 6 1/8 | 0.98 |
| 3 | | SAP# 100070255 | | | | | | |
| 4 | C4079822-4 | MANDREL - ACC | | INT x INT - ACC | | | | |
| 5 | | SAP# 100070268 | | | | | | |
| 6 | B2088144-3 | NUT - ACC | | INT - ACC | | | | |
| 7 | | SAP# 100070269 | | | | | | |
| 8 | B1636548-2 | CASE - ACC | | | INT x INT - ACC | | | |
| 9 | | SAP# 100070251 | | | | | | |
| 10 | AHY147031A-2 | CONNECTOR - ACC | | INT x INT - ACC | | | | |
| 11 | | SAP# 100070252 | | | | | | |
| 12 | BBM195138.2 | TEN. SLEEVE - ACC | | | INT - ACC | | | |
| 13 | | SAP# 100070275 | | | | | | |
| 14 | AHY0474766 | LOWER ADAPTER - ACC | | NC 50 - ACC | INT - ACC | 3 3/4 | 6 1/8 | 1.04 |
| 15 | | | | | | | | |
| 16 | | | | | | | | |
| 17 | | | | | | | | |
| 18 | | | | | | | | |
| 19 | | | | | | | | |
| 20 | | | | | | | | |
| 21 | | | | | | | | |
| 22 | | | | | | | | |
| 23 | | | | | | | | |
| 24 | | | | | | | | |
| 25 | | | | | | | | |
| 26 | | | | | | | | |
| 27 | | | | | | | | |
| 28 | | | | | | | | |
| 29 | | | | | | | | |
| 30 | | | | | | | | |
| 31 | | | | | | | | |
| 32 | | | | | | | | |
| 33 | | | | | | | | |
| 34 | | | | | | | | |
| 35 | | | | | | | | |
| 36 | | | | | | | | |
| 37 | | | | | | | | |
| 38 | | | | | | | | |
| 39 | | | | | | | | |
| 40 | | | | | | | | |

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 5

| Batch # Info. | Connection Inspection | | Body Inspection | | Body Dry M.P.I | |
|----------------|---|--|---|--|---------------------------------------|-------------------------------------|
| 20-B 20B065 | Wet Flour. M.P.I. <input checked="" type="checkbox"/> | Dry M.P.I. <input type="checkbox"/> | Wet Flour. M.P.I. <input checked="" type="checkbox"/> | Residual <input type="checkbox"/> | Dry M.P.I. <input type="checkbox"/> | Residual <input type="checkbox"/> |
| Dry Powder | Vis. Liq. Pen. <input type="checkbox"/> | Residual <input type="checkbox"/> | Vis. Liq. Pen. <input type="checkbox"/> | Continuous <input checked="" type="checkbox"/> | Long. Insp. <input type="checkbox"/> | Continuous <input type="checkbox"/> |
| 7-HF | Flour Liq. Pen. <input type="checkbox"/> | Continuous <input checked="" type="checkbox"/> | Flour Liq. Pen. <input type="checkbox"/> | AC Current <input type="checkbox"/> | Trans. Insp. <input type="checkbox"/> | AC Current <input type="checkbox"/> |
| White Contrast | Long. Insp. <input checked="" type="checkbox"/> | AC Current <input type="checkbox"/> | Long. Insp. <input checked="" type="checkbox"/> | DC Current <input checked="" type="checkbox"/> | | DC Current <input type="checkbox"/> |
| 14-A | Trans. Insp. <input checked="" type="checkbox"/> | DC Current <input checked="" type="checkbox"/> | Trans. Insp. <input checked="" type="checkbox"/> | Visible M.P.I. <input type="checkbox"/> | | |

System Effectiveness: LP-Comparitive Block Dry MP-Castrol Strip Wet MP-Castrol Strip

| Blacklight Inspection | Equipment / Inspector Information |
|--|--|
| Blacklight Intensity: <u>6232</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u> | Equipment Used From Unit # <u>13</u> |
| | Qual. Date(s) MT <u>7/21/2019</u> PT <u>9/21/2021</u> |
| Liquid Penetrant Inspection | 3rd Party Rep: _____ |
| Whitelight: _____ | Signature: _____ |
| Magnaflux Developer: SKD-S2 | Level II Inspector: RIDGE ALBERT |
| Magnaflux Penetrant: <input type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D | Signature: |
| Batch # _____ Dwell Time: _____ min | Signature guarantees final walk thru of job and job site |
| Job Information | |
| B _____ RA _____ V _____ RA _____ D _____ P _____ RA _____ | |

