



**BOTTOM HOLE ASSURANCE, INC.**

*Blacklight, Ultrasonic Wall Thickness,  
& Liquid Penetrant Inspection*

No. IR 51722CPS-1

Email: BHAInc@bottomholeassurance.com  
109 Citron Drive • Youngsville, LA 70592


Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION CPS	AUTHORIZED BY WADE RILEY		INVOICE NO.		
RIG		OCS-G & WELL NO.		PROJECT	P.O. NO. / JOB NO. 1017510006	DATE 5/17/2022		
SERIAL NO.	DESCRIPTION			THREAD GAGE	THREAD GAGE S/N	THREAD GAGE CAL.		
1	4122	4 1/2" VAM TOP P-ACC			1/2-14 NPT	SDM-2866-2	2/4/2022	
2	4125	4 1/2" VAM TOP B-ACC			1/2-14 NPT	SDM-2866-2	2/4/2022	
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								
36								
37								
38								
39								
40								

SUMMARY: INSPECT AS PER: MAN-GL-HAL-HCT-900

Batch # Info.	Connection Inspection		Body Inspection			Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>	
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>	
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>	
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>	
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>			

System Effectiveness: LP-Comparative Block  Dry MP-Castrol Strip  Wet MP-Castrol Strip

Blacklight Inspection			Equipment / Inspector Information		
Blacklight Intensity: 4201	Bath Mixture: 0.25	Whitelight: 0.1	Equipment Used From Unit # 13	Qual. Date(s) MT 7/21/2019	PT
Liquid Penetrant Inspection			3rd Party Rep: _____		
Whitelight: _____			Signature: _____		
Magnaflux Developer: SKD-S2	Magnaflux Penetrant: (Check one)	<input type="checkbox"/> SKL-WP2 <input type="checkbox"/> ZL-60D	Level II Inspector: RIDGE ALBERT		
Batch # _____	Batch # _____		Signature: 		
Dwell Time: _____ min	Dwell Time: _____ min		Signature guarantees final walk thru of job and job site		
Job Information			Customer Rep Signoff: _____		
B _____ RA	V _____ RA	D _____ P _____ RA			