



BOTTOM HOLE ASSURANCE, INC.

No. DIR 51722CW-4

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC
RIG
OCS-G & WELL

FACILITY / LOCATION CLEAN WELL
PROJECT OXY

AUTHORIZED BY TONY FREDRICK
P.O. / JOB # 907762935

INVOICE NO.
DATE: 5/17/2022

Main inspection data table with columns: Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width Pin Neck Lgth, Bevel Diameter, B S R, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia. Float Bore Dia., Bore Back Lgth Float Bore Lgth, Box Thread Length, Counterbore Wall Thickness, Bevel Diameter, B S R, OK or Reject, Remarks. Row 1: 13390590, DRILL TECH, 6.59, 23 1/8, 21 3/4, 3", 6 3/4, 6 3/4, CTM-57, 5.623, 5.844, 6.733, Acc, CTM-57, 5.916, 5.627, 0.410, 6.738, Rej, PITTED THREADS

Remarks: FULL BODY INSP. AS PER BSD-GL-HAL-CWT-201

Customer Rep Signoff:

Bottom section containing inspection details: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, System Effectiveness, Job Information, and signatures.