



BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

No. IR **51722TT-2**

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.		
RIG		OCS-G & WELL NO.		PROJECT MURPHY	P.O. NO. / JOB NO. 907773716	DATE 5/17/2022		
SERIAL NO.	DESCRIPTION			PIN	BOX	I.D.	O.D.	LENGTH
1	EQ# 1025563	5" RD VALVE						
2	BAC1947392-2	LOWER ADAPTER - ACC		3 7/8 CAS- ACC	INT - ACC	2 1/4	5	1.03
3		SAP# 100066686						
4	BAC19A0181-1	TOP COUPLING - ACC		INT - ACC	3 7/8 CAS- ACC	2 1/4	5	1.01
5		SAP# 100066687						
6	KM-11-25085-03	SHEAR MANDREL - (LPI) ACC						
7		SAP# 100066701						
8	3552919-1	RD CASE MOD - (LPI) ACC		INT - ACC	INT - ACC			
9		SAP# 102030558						
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								
36								
37								
38								
39								
40								

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 5

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input checked="" type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparitive Block Dry MP-Castrol Strip Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>2240</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>13</u>
	Qual. Date(s) MT <u>7/21/2019</u> PT <u>9/21/2021</u>
Liquid Penetrant Inspection	3rd Party Rep: _____
Whitelight: <u>100.0</u>	Signature: _____
Magnaflux Developer: SKD-S2 Magnaflux Penetrant: <input checked="" type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D	Level II Inspector: <u>RIDGE ALBERT</u>
Batch # <u>19F16K</u> Batch # <u>19D07K</u>	Signature:
Dwell Time: <u>10</u> min Dwell Time: <u>20</u> min	Signature guarantees final walk thru of job and job site
Job Information	
B <u>RA</u> V <u>RA</u> D <u>RA</u> P <u>RA</u>	