



BOTTOM HOLE ASSURANCE, INC.

No. DIR 51922B6

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON
RIG
OCS-G & WELL

3RD PARTY

FACILITY / LOCATION SPERRY DRILLING
PROJECT

AUTHORIZED BY EDDIE FAUCHEUX
P.O. / JOB # SO#: 907592652-10157

INVOICE NO.
DATE: 5/19/2022

Main inspection data table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various Box dimensions.

Remarks: INSPECTED PER D00685901 REV. T ALL API CONNECTIONS MARKED CW UNLESS OTHERWISE NOTED

Summary and signature section including Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information.