



**BOTTOM HOLE ASSURANCE, INC.**

*Blacklight, Ultrasonic Wall Thickness,  
& Liquid Penetrant Inspection*

No. IR **60122TT-1**

Email: BHAInc@bottomholeassurance.com  
109 Citron Drive • Youngsville, LA 70592


Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.	
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 6/1/2022	
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH
1	EQ# 1025579	5" RD VALVE					
2	BAC20A414-1	TOP COUPLING - ACC		INT - ACC	3 7/8 CAS- ACC	2 1/4	1.08
3		SAP# 100066687					
4	BAC1822818-1	LOWER ADAPTER - ACC		3 7/8 CAS- ACC	INT - ACC	2 1/4	0.91
5		SAP# 100066686					
6	B3216530-03	RD CASE MOD - (LP) ACC		INT - ACC	INT - ACC		
7		SAP# 102030558					
8	B221498.1	SHEAR MANDREL - (LP) ACC					
9		SAP# 100066701					
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 5

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input checked="" type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparitive Block  Dry MP-Castrol Strip  Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>4340</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>13</u> Qual. Date(s) MT <u>7/21/2019</u> PT <u>9/21/2021</u>
<b>Liquid Penetrant Inspection</b> Whitelight: <u>100.0</u>	3rd Party Rep: _____
Magnaflux Developer: SKD-S2 Magnaflux Penetrant: <input checked="" type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D	Signature: _____
Batch # <u>19F16K</u> Batch # <u>19D07K</u>	Level II Inspector: RIDGE ALBERT
Dwell Time: <u>10</u> min Dwell Time: <u>20</u> min	Signature: 
<b>Job Information</b> B <u>RA</u> V <u>RA</u> D <u>RA</u> P <u>RA</u>	Signature guarantees final walk thru of job and job site