



BOTTOM HOLE ASSURANCE, INC.

No. DIR 60922CW-2

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION CLEAN WELL PROJECT LLOG

AUTHORIZED BY TONY FREDRICK P.O. / JOB # 907688424

INVOICE NO. DATE: 6/9/2022

Main inspection data table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Root Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various dimensions for PIN and BOX.

Remarks: CONNECTION INSP. AS PER BSD-GL-HAL-CWT-201 (CONNECTION INSPECTION ONLY) (MACHINE SHOP CONNECTION INSPECTION ONLY)

Customer Rep Signoff:

Bottom section containing inspection details: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, System Effectiveness, Job Information, and Inspector Signature (GAELEN ROBIN).