



BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

No. IR **61622TT-4**

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.		
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 6/16/2022		
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH	
1	EQ# 10315017	7" CHAMP IV PACKER						
2	C3177189-2	UPPER SHOE - ACC						
3		SAP# 100012596						
4	KM-16-34096-02	LOWER SHOE - ACC						
5		SAP# 100071663						
6	AN1873370-72	DRAG BLOCKS - ACC						
7	AN216D67-36	SAP# 100004074						
8	AN1767060-12							
9	AN1768111-70							
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								
36								
37								
38								
39								
40								

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 5

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparitive Block Dry MP-Castrol Strip Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>2241</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>13</u>
	Qual. Date(s) MT <u>7/21/2019</u> PT <u>9/21/2021</u>
Liquid Penetrant Inspection	3rd Party Rep: _____
Whitelight: _____	Signature: _____
Magnaflux Developer: SKD-S2 Magnaflux Penetrant: <input type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D	Level II Inspector: RIDGE ALBERT
Batch # _____ Dwell Time: _____ min	Signature: _____
Job Information	Signature guarantees final walk thru of job and job site
B _____ RA _____ V _____ RA _____ D _____ P _____ RA _____	