



BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

No. IR **62922TT-4**

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592


Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.		
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 6/29/2022		
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH	
1	EQ# 10326854	5" FAS FIL						
2	BAC1875724-1	ADAPTER - ACC			3 7/8" CAS - ACC	2 1/4	5	0.90
3		SAP# 100065595						
4	3461919-1	UPPER SEAT HOLDER - ACC			INT x INT - ACC			
5		SAP# 101236683						
6	BAS1776	SEALING MANDREL - ACC		INT - ACC				
7		SAP# 100065585						
8	AHY147558-1	SHEAR SET SLEEVE - ACC						
9		SAP# 100065587						
10	1728519-2	SHEAR PIN COVER - ACC						
11		SAP# 100065783						
12	3987767-1	SHEAR MANDREL - ACC		INT - ACC	INT - ACC			
13		SAP# 100065590						
14	BAC1970909-1	PRESSURE HOUSING - ACC		INT - ACC	INT - ACC			
15		SAP# 100065594						
16	3421687-1	NIPPLE - ACC		3 7/8" CAS - ACC		2 3/4	5"	0.96
17		SAP# 101211418						
18	BAC1944902-1	STINGER- ACC						
19		SAP# 102239102						
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								
36								
37								
38								
39								
40								

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 5

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparitive Block Dry MP-Castrol Strip Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>5169</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>13</u> Qual. Date(s) MT <u>7/21/2019</u> PT <u>9/21/2021</u>
Liquid Penetrant Inspection Whitelight: _____ Magnaflux Developer: SKD-S2 Magnaflux Penetrant: <input type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D Batch # _____ Batch # _____ Dwell Time: _____ min Dwell Time: _____ min	3rd Party Rep: _____ Signature: _____ Level II Inspector: RIDGE ALBERT Signature: 
Job Information B _____ RA _____ V _____ RA _____ D _____ P _____ RA _____	Signature: _____ <small>Signature guarantees final walk thru of job and job site</small>