BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

No. IR **62422CWP-1**

CUSTOMER	3rd PARTY	FACILITY / LOCATION	AUTHORIZED BY	INVOICE NO.
HALLIBURTON ICC	☐	CLEAN WELL	TONY FREDRICK	

RIG	OCS-G & WELL NO.	PROJECT	P.O. NO. / JOB NO.	DATE
				6/24/2022

	SERIAL NO.	DESCRIPTION	ACC / REJ.		SERIAL NO.	DESCRIPTION	ACC / REJ.
1	45147648313	SPRING CARTRIDGE	ACC	41			
2	45147648312	SPRING CARTRIDGE	ACC	42			
3				43			
4				44			
5				45			
6				46			
7				47			
8				48			
9				49			
10				50			
11				51			
12				52			
13				53			
14				54			
15				55			
16				56			
17				57			
18				58			
19				59			
20				60			
21				61			
22				62			
23				63			
24				64			
25				65			
26				66			
27				67			
28				68			
29				69			
30				70			
31				71			
32				72			
33				73			
34				74			
35				75			
36				76			
37				77			
38				78			
39				79			
40				80			

SUMMARY: FULL BODY INSP AS PER BSD-GL-HAL-CWT-201

Batch # Info.		Connection Inspection				Body Inspection				Body Dry M.P.I			
20-B	20B065	Wet Flour. M.P.I.	☐	Dry M.P.I.	☐	Wet Flour. M.P.I.	☑	Residual	☐	Dry M.P.I.	☐	Residual	☐
Dry Powder		Vis. Liq. Pen.	☐	Residual	☐	Vis. Liq. Pen.	☐	Continuous	☑	Long. Insp.	☐	Continuous	☐
7-HF		Flour Liq. Pen.	☐	Continuous	☐	Flour Liq. Pen.	☐	AC Current	☐	Trans. Insp.	☐	AC Current	☐
White Contrast		Long. Insp.	☐	AC Current	☐	Long. Insp.	☑	DC Current	☑			DC Current	☐
14-A		Trans. Insp.	☐	DC Current	☐	Trans. Insp.	☑	Visible M.P.I.	☐				

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑

Blacklight Inspection

Blacklight Intensity: 4916 Bath Mixture: 0.30 Whitelight: 0.1

Liquid Penetrant Inspection

Whitelight: _____

Magnaflux Developer: SKD-S2

Magnaflux Penetrant: (Check one) ☐ SKL-WP2 ☐ ZL-60D

Batch # _____ Batch # _____

Dwell Time: min Dwell Time: min

Job Information

B GR V GR D _____ P BP

Equipment / Inspector Information

Equipment Used From Unit # 32

Qual. Date(s) MT 11/30/2021 PT _____

3rd Party Rep: _____

Signature: _____

Level II Inspector: GAELEN ROBIN

Signature: _____

Signature guarantees final walk thru of job and job site

E-IR03-03

REVIEWED
By David Patin at 7:30 am, Jul 01, 2022