



BOTTOM HOLE ASSURANCE, INC.

BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

No. DIR 62822ST-2

CUSTOMER HALLIBURTON ICC 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION SERVICE TOOLS PROJECT KOSMOS

AUTHORIZED BY DERRICK ROBIN P.O. / JOB # 907664162

INVOICE NO. DATE: 6/28/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia., Float Bore Dia., Bore Back Lgth, Float Bore Lgth, Box Thread Length, Counterbore Wall Thickness, Bore Diameter, BSR, OK or Reject, Remarks.

Stamp: PPI M R DATE 6/28/2022 040

Remarks: FULL BODY INSP. AS PER WM-GL-HAL-HCT-900 REV. 0 (TOOL COMPONENT INSPECTION ONLY, NOT COMPLETE TOOL)

Inspection summary form with sections: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, Job Information.

REVIEWED By David Patin at 7:43 am, Jun 29, 2022