



BOTTOM HOLE ASSURANCE, INC.

No. DIR 63022HMM1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC
RIG MAD DOG
OCS-G & WELL 15610 & # 14, G.C. 742

FACILITY / LOCATION HARD METAL MILLS / SERVICE TOOLS
PROJECT BP

AUTHORIZED BY MIKE ANDRUS
P.O. / JOB #

INVOICE NO.
DATE: 6/30/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various dimensions for PIN and BOX.

Remarks: FULL BODY INSP AS PER MAN-GL-HAL-HCT-900 REV. 2

Customer Rep Signoff:

Inspection summary form including sections for Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information.