



BOTTOM HOLE ASSURANCE, INC.

No. DIR 71222B1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON 3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION SPERRY DRILLING
PROJECT

AUTHORIZED BY EDDIE FAUCHEUX
P.O. / JOB # 907749929

INVOICE NO.
DATE: 7/13/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various dimensions for PIN and BOX.

Remarks: INSPECTED PER D00686901 REV. T

Inspection summary and equipment information section including tables for Connection, Body, Body Dry M.P.I., Blacklight, and Liquid Penetrant inspection results, along with equipment and inspector details.