



BOTTOM HOLE ASSURANCE, INC.

No. DIR 71322SB3

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER SBES 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION SHOP PROJECT

AUTHORIZED BY KALE P.O. / JOB # W/O# 324005451

INVOICE NO. DATE: 7/13/2022

Main inspection data table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various Box dimensions.

Remarks: INSP AS PER D00685901 REV. T ALL CONNECTIONS MARKED WITH CW STAMP UNLESS NOTED OTHERWISE N1 - VISUAL AND DIMENSIONAL OF REFACED CONN ONLY Customer Rep Signoff:

Bottom section containing inspection details: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information.