# BOTTOM HOLE ASSURANCE, INC.

No. DIR 50224B3


NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com


CUSTOMER Halliburton ☐ 3RD PARTY | FACILITY / LOCATION Sperry Drilling | AUTHORIZED BY Kale Veronie | INVOICE NO.

RIG | PROJECT | P.O. / JOB # 907379155 | DATE: 5/2/2024

OCS-G & WELL

| | | | | | | | | PIN | | | | | | | | | | BOX | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Serial # | Tool Description | Overall Length | Fishing Neck Length | Tong Space | Pin I.D. | Pin O.D. | Box O.D. | Connection Size | Pin Length | Pin Cylinder Diameter | Pin Nose Diameter | Pin Relief Diameter | Pin Rel. Width Pin Neck Lgth | Bevel Diameter | B S R | OK or Reject | Remarks | Connection Size | Counter Bore Length | Counter Bore Diameter | Bore Back Dia. Float Bore Dia. | Bore Back Lgth Float Bore Lgth | Box Thread Length | Counterbore Wall Thickness | Bevel Diameter | B S R | OK or Reject | Remarks |
| SN: 14071878 PN: 103076242 | 12.125" SLEEVE STABILIZER | | | | | | | Blades | | | | | | | | Rej | Damaged | ACME | | | | | | | | | OK | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SN: CP2977538 PN: 321376 | 12.125" SLEEVE STABILIZER | | | | | | | Blades | | | | | | | | Rej | Damaged | ACME | | | | | | | | | OK | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

**Remarks:** Inspection as per DS1 & D00685901 Rev. W NOTE: All API connections show evidence of Cold Work unless otherwise noted.

Customer Rep Signoff:

**Batch # Info.**

| | |
|---|---|
| 20-B | |
| Dry Powder | |
| 7-HF | |
| White Contrast | |
| 14-A | |

**Connection Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☐ | Dry M.P.I. | ☐ |
| Vis. Liq. Pen. | ☑ | Residual | ☐ |
| Flour Liq. Pen. | ☐ | Continuous | ☐ |
| Long. Insp. | ☐ | AC Current | ☐ |
| Trans. Insp. | ☐ | DC Current | ☐ |

**Body Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☐ | Residual | ☐ |
| Vis. Liq. Pen. | ☑ | Continuous | ☐ |
| Flour Liq. Pen. | ☐ | AC Current | ☐ |
| Long. Insp. | ☐ | DC Current | ☐ |
| Trans. Insp. | ☐ | Visible M.P.I. | ☐ |

**Body Dry M.P.I**

| | | | |
|---|---|---|---|
| Dry M.P.I. | ☐ | Residual | ☐ |
| Long. Insp. | ☐ | Continuous | ☐ |
| Trans. Insp. | ☐ | AC Current | ☐ |
| | | DC Current | ☐ |

System Effectiveness: LP-Comparitive Block ☑ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☐ Profile Gage RSC OK ☑

**Job Information**

B V D P

3rd Party Rep

Woodfred Zechariah

Signature:

**Blacklight Inspection**

Blacklight Intensity: Bath Mixture: Whitelight:

**Equipment / Inspector Information**

Equipment Used From Unit # 14

Qual. Date(s) MT 7/21/2019 PT 7/30/2021

Level II Inspector: Ridge Albert

Signature: Ridge Albert

Signature guarantees final walk thru of job and job site

**Liquid Penetrant Inspection**

Magnaflux Developer: SKD-S2

Batch # 23M08C

Dwell Time: 10 min

White Light: 100+

Magnaflux Penetrant: (Check one) ☑ SKL-WP2 ☐ ZL-60D

Batch # 23L075

Dwell Time: 20 min