No. DIR 50224B5

BOTTOM HOLE ASSURANCE, INC.

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER Halliburton ☐ 3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION Sperry Drilling
PROJECT

AUTHORIZED BY Zachary Dudley
P.O. / JOB # 909194492

INVOICE NO.
DATE: 5/2/2024

Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	PIN Connection Size	PIN Pin Length	PIN Pin Cylinder Diameter	PIN Pin Nose Diameter	PIN Pin Relief Diameter	PIN Pin Rel. Width Pin Neck Lgth	PIN Bevel Diameter	PIN B S R	PIN OK or Reject	PIN Remarks	BOX Connection Size	BOX Counter Bore Length	BOX Counter Bore Diameter	BOX Bore Back Dia. Float Bore Dia.	BOX Bore Back Lgth Float Bore Lgth	BOX Box Thread Length	BOX Counterbore Wall Thickness	BOX Bevel Diameter	BOX B S R	BOX OK or Reject	BOX Remarks
7600 - 360	7600 SERIES GEO-PILOT																											
2720502	OLDHAM PLATE															OK												
3337524	OLDHAM CLUTCH HUB															OK												
1935809	CLUTCH COUPLING															OK												
2356434	LOCKNUT TENSION															OK												
1851847	LOCKNUT COMPRESSION															OK												
12342808	CIM HANGER															OK												

Remarks: Inspection as per DS1 & D00685901 Rev. W NOTE: All API connections show evidence of Cold Work unless otherwise noted.

Customer Rep Signoff:

Batch # Info.

20-B	21J002
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☑	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☑
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☑	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☑
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

System Effectiveness: LP-Comparitive Block ☑ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Job Information

B V D P

3rd Party Rep
Woodfred Zechariah
Signature:

Blacklight Inspection

Blacklight Intensity: 6150 Bath Mixture: 0.25 Whitelight: 0.0

Equipment / Inspector Information

Equipment Used From Unit # 14
Qual. Date(s) MT 7/21/2019 PT 7/30/2021

Level II Inspector: Ridge Albert
Signature: Ridge Albert
Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch # 23M08C
Dwell Time: 10 min
White Light: 100+
Magnaflux Penetrant: (Check one) ☑ SKL-WP2 ☐ ZL-60D
Batch # 23L075
Dwell Time: 20 min