



BOTTOM HOLE ASSURANCE, INC.

NDE Inspection Services

No. IR 50624TT-4

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592


Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.	
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 5/6/2024	
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH
1	EQ# 12207926	5" BIG JOHN JAR					
2	3677609-2	TOP COUPLING - ACC		INT (B) - ACC	3 7/8" CAS - ACC	2 1/4	5 0.98
3		SAP# 100066624					
4	BAC20A0270-1	SPLINED HOUSING - ACC		INT - ACC			
5		SAP# 100066622					
6	0003870156-1	IMPACT MANDREL - ACC		INT - ACC	INT - ACC		
7		SAP# 100066605					
8	BBM-194636-3	CASE - ACC			INT x INT - ACC		
9		SAP# 100066625					
10	3707878-2	METERING SLEEVE - ACC					
11		SAP# 100066616					
12	2897196-1	METERING NUT - (ALL ACCESSIBLE AREAS) ACC					
13		SAP# 100066608					
14	3531236-2	EQUALIZING PRESSURE PISTON - ACC					
15		SAP# 100066609					
16	BAC21A0012-1	LOWER MANDREL - ACC			INT - ACC		
17		SAP# 100066618					
18	3212092-2	BOTTOM NIPPLE - ACC		3 7/8" CAS x INT - ACC		2 1/4	5 0.63
19		SAP# 100066626					
20	AEZ141477-4	ADJUSTMENT METER CONE - (ALL ACCESSIBLE AREAS) ACC		INT x INT - ACC			
21		SAP# 100066617					
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 6

Batch # Info.	Connection Inspection		Body Inspection			Body Dry M.P.I	
20-B 23K007	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>	
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>	
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>	
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>	
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>			

System Effectiveness: LP-Comparative Block Dry MP-Castrol Strip Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: 3681 Bath Mixture: 0.25 Whitelight: 0.1	Equipment Used From Unit # 13 Qual. Date(s) MT 2/16/2023 PT 8/9/2023
Liquid Penetrant Inspection Whitelight: _____ Magnaflex Developer: SKD-S2 Magnaflex Penetrant: (Check one) <input type="checkbox"/> SKL-WP2 <input type="checkbox"/> ZL-60D Batch # _____ Batch # _____ Dwell Time: _____ min Dwell Time: _____ min	3rd Party Rep: _____ Signature: _____ Level II Inspector: BRONZE POIRIER Signature:  <small>Signature guarantees final walk thru of job and job site</small>
Job Information B _____ BP _____ V _____ BP _____ D _____ P _____ BP _____	Customer Rep Signoff: _____