

BOTTOM HOLE ASSURANCE, INC.

No. DIR 50322SB5



Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER SBES 3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION Shop
PROJECT Halliburton Sperry Drilling

AUTHORIZED BY Kale Veronie
P.O. / JOB # WO# 323736434

INVOICE NO.
DATE: 5/3/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and additional measurements for PIN and BOX.

Remarks: Inspection as per D00685901 Rev. T
NOTE: Reworked API connection shows evidence of Cold Work
Customer Rep Signoff:
Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, Job Information, and Signature fields.