# BOTTOM HOLE ASSURANCE, INC.

No. DIR 50422B3

*Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection*

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592
Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ☐ 3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION SPERRY DRILLING
PROJECT

AUTHORIZED BY RYAN BROUSSARD
P.O. / JOB # WO#: 322892378

INVOICE NO.
DATE: 5/4/2022

| Serial # | Tool Description | Overall Length | Fishing Neck Length | Tong Space | Pin I.D. | Pin O.D. | Box O.D. | PIN Connection Size | PIN Pin Length | PIN Pin Cylinder Diameter | PIN Pin Nose Diameter | PIN Pin Relief Diameter | PIN Pin Rel. Width Pin Neck Lgth | PIN Bevel Diameter | PIN B S R | PIN OK or Reject | PIN Remarks | BOX Connection Size | BOX Counter Bore Length | BOX Counter Bore Diameter | BOX Bore Back Dia. Float Bore Dia. | BOX Bore Back Lgth Float Bore Lgth | BOX Box Thread Length | BOX Counterbore Wall Thickness | BOX Bevel Diameter | BOX B S R | BOX OK or Reject | BOX Remarks |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SN: 3100162 PN: 102444458 | SEAL CARRIER ADAPTER CAP | | | | | | | | | | | | | | | OK | | | | | | | | | | | | |
| SN: 2988406 PN: 102444455 | SEAL CARRIER ADAPTER | | | | | | | | | | | | | | | OK | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

**Remarks:** INSPECTED PER D00685901 REV. T

ALL API CONNECTIONS MARKED CW UNLESS OTHERWISE NOTED

**Batch # Info.**

| | |
|---|---|
| 20-B | 20B065 |
| Dry Powder | |
| 7-HF | |
| White Contrast | |
| 14-A | |

**Connection Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☑ | Dry M.P.I. | ☐ |
| Vis. Liq. Pen. | ☑ | Residual | ☐ |
| Flour Liq. Pen. | ☐ | Continuous | ☑ |
| Long. Insp. | ☐ | AC Current | ☐ |
| Trans. Insp. | ☑ | DC Current | ☑ |

**Body Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☑ | Residual | ☐ |
| Vis. Liq. Pen. | ☑ | Continuous | ☑ |
| Flour Liq. Pen. | ☐ | AC Current | ☑ |
| Long. Insp. | ☑ | DC Current | ☐ |
| Trans. Insp. | ☑ | Visible M.P.I. | ☐ |

**Body Dry M.P.I**

| | | | |
|---|---|---|---|
| Dry M.P.I. | ☐ | Residual | ☐ |
| Long. Insp. | ☐ | Continuous | ☐ |
| Trans. Insp. | ☐ | AC Current | ☐ |
| | | DC Current | ☐ |

System Effectiveness: LP-Comparitive Block ☑ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

3rd Party Rep

**Job Information**

B V D P

Signature:

**Blacklight Inspection**

Blacklight Intensity: 6500 Bath Mixture: 0.25 Whitelight: 0.0

**Equipment / Inspector Information**

Equipment Used From Unit # 14
Qual. Date(s) MT 11/11/2019 PT 11/11/2019

Level II Inspector: DUSTIN KNIGHT

Signature: Dustin Knight

Signature guarantees final walk thru of job and job site

**Liquid Penetrant Inspection**

Magnaflux Developer: SKD-S2
Batch # 21A02U
Dwell Time: 10 min
White Light: 100+
Magnaflux Penetrant: ☑ SKL-WP2
(Check one) ☐ ZL-60D
Batch # 21A077
Dwell Time: 20 min

E-DIR01-04