# BOTTOM HOLE ASSURANCE, INC.

No. DIR 50422B6

*Blacklight, Ultrasonic Wall Thickness,*
*& Liquid Penetrant Inspection*

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592
Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ☐ 3RD PARTY | FACILITY / LOCATION SPERRY DRILLING | AUTHORIZED BY RYAN BROUSSARD | INVOICE NO.

RIG | PROJECT | P.O. / JOB # WO#: 323745573 | DATE: 5/4/2022

OCS-G & WELL

| | | | | | | | | PIN | | | | | | | | | BOX | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Serial # | Tool Description | Overall Length | Fishing Neck Length | Tong Space | Pin I.D. | Pin O.D. | Box O.D. | Connection Size | Pin Length | Pin Cylinder Diameter | Pin Nose Diameter | Pin Relief Diameter | Pin Rel. Width Pin Neck Lgth | Bevel Diameter | B S R | OK or Reject | Remarks | Connection Size | Counter Bore Length | Counter Bore Diameter | Bore Back Dia. Float Bore Dia. | Bore Back Lgth Float Bore Lgth | Box Thread Length | Counterbore Wall Thickness | Bevel Diameter | B S R | OK or Reject | Remarks |
| SN: 1665525 PN: 101340678 | 8.500" PAD | | | | | | | | | | | | | | | OK | | | | | | | | | | | |
| SN: 1665467 PN: 101340678 | 8.500" PAD | | | | | | | | | | | | | | | OK | | | | | | | | | | | |
| SN: 1665470 PN: 101340678 | 8.500" PAD | | | | | | | | | | | | | | | OK | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | |

**Remarks:** INSPECTED PER D00685901 REV. T ALL API CONNECTIONS MARKED CW UNLESS OTHERWISE NOTED

**Batch # Info.**

| | |
|---|---|
| 20-B | 20B065 |
| Dry Powder | |
| 7-HF | |
| White Contrast | |
| 14-A | |

**Connection Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☐ | Dry M.P.I. | ☐ |
| Vis. Liq. Pen. | ☐ | Residual | ☐ |
| Flour Liq. Pen. | ☐ | Continuous | ☐ |
| Long. Insp. | ☐ | AC Current | ☐ |
| Trans. Insp. | ☐ | DC Current | ☐ |

**Body Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☑ | Residual | ☐ |
| Vis. Liq. Pen. | ☐ | Continuous | ☑ |
| Flour Liq. Pen. | ☐ | AC Current | ☑ |
| Long. Insp. | ☑ | DC Current | ☐ |
| Trans. Insp. | ☑ | Visible M.P.I. | ☐ |

**Body Dry M.P.I**

| | | | |
|---|---|---|---|
| Dry M.P.I. | ☐ | Residual | ☐ |
| Long. Insp. | ☐ | Continuous | ☐ |
| Trans. Insp. | ☐ | AC Current | ☐ |
| | | DC Current | ☐ |

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☐

3rd Party Rep

**Job Information**

B V D P

Signature:

**Blacklight Inspection**

Blacklight Intensity: 6500 Bath Mixture: 0.25 Whitelight: 0.0

**Equipment / Inspector Information**

Equipment Used From Unit # 14

Qual. Date(s) MT 11/11/2019 PT

Level II Inspector: DUSTIN KNIGHT

Signature: *Dustin Knight*

Signature guarantees final walk thru of job and job site

**Liquid Penetrant Inspection**

Magnaflux Developer: SKD-S2

Batch #

Dwell Time: min

White Light:

Magnaflux Penetrant: ☐ SKL-WP2
(Check one) ☐ ZL-60D

Batch #

Dwell Time: min