



BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION SERVICE TOOLS PROJECT ANADARKO

AUTHORIZED BY DERRICK ROBIN P.O. / JOB # 903659625

INVOICE NO. DATE: 5/11/2022

Main data table with columns for PIN and BOX inspection parameters, including Serial #, Tool Description, Overall Length, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, B S R, OK or Reject, Remarks, and various diameter/length measurements.

Remarks: FULL BODY INSP. AS PER WM-GL-HAL-HCT-900 REV. 0

Summary form containing Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information sections.

REVIEWED By David Patin at 4:19 pm, May 17, 2022