



BOTTOM HOLE ASSURANCE, INC.

No. DIR 51222ST-1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION SERVICE TOOLS PROJECT IN HOUSE

AUTHORIZED BY DERRICK ROBIN P.O. / JOB # 1017510021

INVOICE NO. DATE: 5/12/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, B S R, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia. Float Bore Dia., Bore Back Lgth, Box Thread Length, Counterbore Wall Thickness, Bevel Diameter, B S R, OK or Reject, Remarks.

Remarks: FULL BODY INSP. AS PER WM-GL-HAL-HCT-900 REV. 0 (TOOL COMPONENT INSPECTION ONLY, NOT COMPLETE TOOL)

Inspection summary form including sections for Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information.

REVIEWED By David Patin at 4:50 pm, May 17, 2022

