BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592
Office: (337) 857-8994 Fax: (337) 857-8964

No. DIR 51222ST-3

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY DERRICK ROBIN | INVOICE NO.
RIG | PROJECT BHP | P.O. / JOB # 907684841 | DATE: 5/12/2022
OCS-G & WELL

								PIN										BOX									
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 10323667	6 1/2" BY PASS																											
630228-1	COUPLING SAP# 100064924	0.83	8 7/8	-	3 1/16	-	6 1/4	INT (B)								Acc		NC 50	11/16	5 5/16					6 1/16	-	Acc	
B448811-3	LUG MANDREL SAP# 100070288							INT								Acc		INT									Acc	
3264161-1	J-SLOT SLEEVE SAP# 100070286																	INT									Acc	
KM1431686-02	PORT MANDREL SAP# 100070283																	INT									Acc	
KM1532283-03	BODY SAP# 100070282							INT								Acc		INT									Acc	
B735425-1	LOWER BODY SAP# 100070289	1.32	-	15 15/16	3 3/4	6 1/4	-	NC 50	4 3/8				5/16	6 1/16	-	Acc		INT (P)									Acc	

Remarks: FULL BODY INSP. AS PER WM-GL-HAL-HCT-900 REV. 0

Batch # Info.
20-B 20B065
Dry Powder
7-HF
White Contrast
14-A

Connection Inspection
Wet Flour. M.P.I. ☑ Dry M.P.I. ☐
Vis. Liq. Pen. ☐ Residual ☐
Flour Liq. Pen. ☐ Continuous ☑
Long. Insp. ☑ AC Current ☐
Trans. Insp. ☑ DC Current ☐

Body Inspection
Wet Flour. M.P.I. ☑ Residual ☐
Vis. Liq. Pen. ☐ Continuous ☑
Flour Liq. Pen. ☐ AC Current ☐
Long. Insp. ☑ DC Current ☑
Trans. Insp. ☑ Visible M.P.I. ☐

Body Dry M.P.I
Dry M.P.I. ☐ Residual ☐
Long. Insp. ☐ Continuous ☐
Trans. Insp. ☐ AC Current ☐
DC Current ☐

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Job Information
B BT V BT D P BT

3rd Party Rep
Signature: HB71807

Blacklight Inspection
Blacklight Intensity: 8700 Bath Mixture: 0.30 Whitelight: 0.1

Equipment / Inspector Information
Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2019 PT 4/26/2019
Level II Inspector: BRANSON THERIOT
Signature:
Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection
Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2
(Check one) ☐ ZL-60D
Batch #
Dwell Time: min

REVIEWED
By David Patin at 4:50 pm, May 17, 2022