



BOTTOM HOLE ASSURANCE, INC.

No. DIR 51322CW-1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION CLEAN WELL PROJECT ENVEN

AUTHORIZED BY TONY FREDRICK P.O. / JOB # 907672320

INVOICE NO. DATE: 5/13/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia., Bore Back Lgth, Float Bore Lgth, Box Thread Length, Counterbore Wall Thickness, Bevel Diameter, BSR, OK or Reject, Remarks.

Remarks: FULL BODY INSP. AS PER BSD-GL-HAL-CWT-201. Inspection summary table with sections: Batch # Info., Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection. Includes fields for System Effectiveness, Job Information, Equipment Used, and Inspector Signature (GAELEN ROBIN).