



BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION SERVICE TOOLS PROJECT BHP

AUTHORIZED BY DERRICK ROBIN P.O. / JOB # 906971651

INVOICE NO. DATE: 5/15/2022

Main inspection data table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, B S R, OK or Reject, Remarks, and various Box dimensions.

Remarks: FULL BODY INSP. AS PER WM-GL-HAL-HCT-900 REV. 0

Inspection summary and signature section including Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, and Liquid Penetrant Inspection details.

REVIEWED By David Patin at 8:07 am, May 18, 2022