



BOTTOM HOLE ASSURANCE, INC.

No. DIR 51622B1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON
RIG
OCS-G & WELL

3RD PARTY

FACILITY / LOCATION SPERRY DRILLING
PROJECT

AUTHORIZED BY EDDIE FAUCHEUX
P.O. / JOB # CC#: 1016910157

INVOICE NO.
DATE: 5/16/2022

Main inspection data table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various dimensions for PIN and BOX sections.

Remarks: INSPECTED PER D00685901 REV. T ALL API CONNECTIONS MARKED CW UNLESS OTHERWISE NOTED

Bottom section containing inspection details: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information.