



B O T T O M H O L E A S S U R A N C E , I N C .

No. DIR **51622B8**

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ☐ 3RD PARTY

RIG

OCS-G & WELL

FACILITY / LOCATION SPERRY DRILLING

PROJECT

AUTHORIZED BY EDDIE FAUCHEUX

P.O. / JOB # SO#: 907592652-10157

INVOICE NO.

DATE: 5/16/2022

[illegible]

Remarks: INSPECTED PER D00685901 REV. T

ALL API CONNECTIONS MARKED CW UNLESS OTHERWISE NOTED

Batch # Info.		Connection Inspection		Body Inspection		Body Dry M.P.I.		Blacklight Inspection			Liquid Penetrant Inspection				
Dry Powder	20-B	Wet Flour. M.P.I.	<input type="checkbox"/>	Dry M.P.I.	<input type="checkbox"/>	Wet Flour. M.P.I.	<input type="checkbox"/>	Residual	<input type="checkbox"/>	Dry M.P.I.	<input type="checkbox"/>	Residual	<input type="checkbox"/>	Blacklight Intensity: _____ Bath Mixture: _____ Whitelight: _____	Magnaflux Developer: SKD-S2
		Vis. Liq. Pen.	<input checked="" type="checkbox"/>	Residual	<input type="checkbox"/>	Vis. Liq. Pen.	<input checked="" type="checkbox"/>	Continuous	<input type="checkbox"/>	Long. Insp.	<input type="checkbox"/>	Continuous	<input type="checkbox"/>	Batch # 22A07	
	7-HF	Flour Liq. Pen.	<input type="checkbox"/>	Continuous	<input type="checkbox"/>	Flour Liq. Pen.	<input type="checkbox"/>	AC Current	<input type="checkbox"/>	Trans. Insp.	<input type="checkbox"/>	AC Current	<input type="checkbox"/>	Equipment / Inspector Information	Dwell Time: 10 min
White Contrast		Long. Insp.	<input type="checkbox"/>	AC Current	<input type="checkbox"/>	Long. Insp.	<input type="checkbox"/>	DC Current	<input type="checkbox"/>	Equipment Used From Unit # 14			White Light: 100+		
	14-A	Trans. Insp.	<input type="checkbox"/>	DC Current	<input type="checkbox"/>	Trans. Insp.	<input type="checkbox"/>	Visible M.P.I.	<input type="checkbox"/>	Qual. Date(s) MT _____ PT 11/11/2019			Magnaflux Penetrant: <input checked="" type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D		
System Effectiveness:		LP-Comparative Block	<input checked="" type="checkbox"/>	Dry MP-Castrol Strip	<input type="checkbox"/>	Wet MP-Castrol Strip	<input type="checkbox"/>	Profile Gage RSC OK <input checked="" type="checkbox"/>		Level II Inspector: DUSTIN KNIGHT			Batch # 22B056		
Job Information						3rd Party Rep _____			Signature: _____			Dwell Time: 20 min			
B _____ V _____ D _____ P _____									Signature: <i>Dustin Knight</i> Signature guarantees final walk thru of job and job site						