



BOTTOM HOLE ASSURANCE, INC.

No. DIR 51822TT-8

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC 3RD PARTY
RIG _____
OCS-G & WELL _____

FACILITY / LOCATION TEST TOOLS
PROJECT BP

AUTHORIZED BY BOBBY CHOATE
P.O. / JOB # 907802898

INVOICE NO. _____
DATE: 5/18/2022

Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	PIN								BOX								Remarks				
								Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length		Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject
617-1079	X-OVER	1.40	13 1/8	12 7/8	2 1/4	5	7	3 7/8 CAS	-	-	-	-	-	-	-	Acc		CTM 57	-	5.936	-	-	5.630	.536	6.734	-	Acc	
617-1108	X-OVER	1.43	15	13	2 1/4	5	7	3 7/8 CAS	-	-	-	-	-	-	-	Acc		CTM 57	-	5.924	-	-	5.625	.550	6.754	-	Acc	
617-1112	X-OVER	2.46	15 15/16	12 15/16	2 1/4	5	7	CTM 57	5.623	5.851	-	-	-	6.732	-	Rej	DAMAGED 15° SEAL	3 7/8 CAS	-	-	-	-	-	-	-	-	Acc	
HMA-1003	X-OVER	1.77	FL	FL	3 3/4	5	7	NC 50	4 7/16	-	-	-	3/16	6 5/64	-	Acc		5 1/4 CAS	-	-	-	-	-	-	-	-	Acc	