



BOTTOM HOLE ASSURANCE, INC.

No. DIR 51922TT-1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC
RIG
OCS-G & WELL

3RD PARTY

FACILITY / LOCATION TEST TOOLS
PROJECT MURPHY

AUTHORIZED BY BOBBY CHOATE
P.O. / JOB # 907850196

INVOICE NO.
DATE: 5/19/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Root Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various dimensions for PIN and BOX.

Remarks: FULL BODY INSP. AS PER BSM-GOM-HAL-TT-201 REV. 5

Inspection summary table with sections: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment Used From Unit #, and Job Information.

E-DIR01-04

REVIEWED
By David Patin at 10:23 am, May 23, 2022