



BOTTOM HOLE ASSURANCE, INC.

No. DIR 52022ST-1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC
RIG
OCS-G & WELL

FACILITY / LOCATION SERVICE TOOLS
PROJECT SHELL

AUTHORIZED BY DERRICK ROBIN
P.O. / JOB # 907744955

INVOICE NO.
DATE: 5/20/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, B S R, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia. Float Bore Dia., Bore Back Lgth Float Bore Lgth, Box Thread Length, Counterbore Wall Thickness, Bevel Diameter, B S R, OK or Reject, Remarks.

Remarks: CONNECTION INSP. AS PER WM-GL-HAL-HCT-900 REV. 0 (MACHINE SHOP CONNECTION INSPECTION ONLY)

Inspection summary table with sections: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, Job Information, and signatures.

REVIEWED
By David Patin at 2:37 pm, May 23, 2022