



BOTTOM HOLE ASSURANCE, INC.

No. DIR 52422SB1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER S.B.E.S. 3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION Shop
PROJECT

AUTHORIZED BY Melvin
P.O. / JOB # WO# 323806997

INVOICE NO.
DATE: 5/24/2022

Main inspection data table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various Box dimensions.

Remarks: Insp As Per D00685901 Rev: T Cw Stamped Customer Rep Signoff:

Bottom section containing inspection details, equipment information, inspector signature (Levar Eaglin), and job information.