



BOTTOM HOLE ASSURANCE, INC.

No. DIR 60322CW-2

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC
3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION CLEAN WELL
PROJECT IN HOUSE

AUTHORIZED BY TONY FREDRICK
P.O. / JOB # 1017510183

INVOICE NO.
DATE: 6/3/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Root Width, Bevel Diameter, BSR, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia. Float Bore Dia., Bore Back Lgh Float Bore Lgh, Box Thread Length, Counterbore Wall Thickness, Bevel Diameter, BSR, OK or Reject, Remarks.

Remarks: CONNECTION INSP. AS PER BSD-GL-HAL-CWT-201 (CONNECTION INSPECTION ONLY) (MACHINE SHOP CONNECTION INSPECTION ONLY)

Customer Rep Signoff:

Batch # Info., Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment Used From Unit #, Qual. Date(s), System Effectiveness, Job Information, Signature: GAELEN ROBIN