



BOTTOM HOLE ASSURANCE, INC.

No. DIR 60622B3

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAinc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON 3RD PARTY

FACILITY / LOCATION SPERRY DRILLING

AUTHORIZED BY EDDIE FAUCHEAUX

INVOICE NO.

RIG ENSCO 8505

PROJECT KOSMOS

P.O. / JOB # 907461971-10157

DATE: 6/16/2022

OCS-G & WELL

Table with columns for Pin and Box dimensions and inspection results. Includes rows for various pin sizes like 6 3/4" X-OVER and 6 3/4" CONVERSION SUB.

Remarks: INSPECTED AS PER D00685901 REV. T

Inspection Summary and Job Information section. Includes fields for Batch # Info, Connection Inspection, Body Inspection, Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, and Job Information.



Signature: Dustin Knight

Signature guarantees full walk thru of job and job site