BOTTOM HOLE ASSURANCE, INC.

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592
Office: (337) 857-8994 Fax: (337) 857-8964

No. DIR 60622B4

CUSTOMER HALLIBURTON ☑ 3RD PARTY
RIG ENSCO 8505
OCS-G & WELL

FACILITY / LOCATION SPERRY DRILLING
PROJECT KOSMOS

AUTHORIZED BY EDDIE FAUCHEAUX
P.O. / JOB # 907461971-10157

INVOICE NO.
DATE: 6/6/2022

								PIN										BOX											
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
SN: 10780795 PN: 120165325	6 3/4" X-OVER	1.46	FL	FL	3"	6 3/4		NC50	4 7/16				1/4	6 9/32		OK		NC50										
						6 3/4		NC50	4 7/16				3/8	6 11/32		OK												
SN: 11263197 PN: 101276155	6 3/4" X-OVER	1.60	9"	8 5/8	3"	6 11/16		NC50	4 7/16				5/16	6 5/16		OK												
						7 7/16		6 5/8 REG	4 15/16				5/16	7 3/16		OK												
SN: 12989881 PN: 101376368	8 1/4" STABILIZER							Blades								OK		ACME									OK	
SN: 12321391 PN: 101376368	8 1/4" STABILIZER							Blades								OK		ACME									OK	
SN: 13531753 PN: 101345755	8 3/8" STABILIZER							Blades								OK		ACME									OK	

Remarks: INSPECTED AS PER D00605901 REV. T

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I		Blacklight Inspection	Liquid Penetrant Inspection
20-B	Wet Flour. M.P.I. ☐	Dry MPI ☐	Wet Flour. MPI ☐	Residual ☐	Dry MPI ☐	Residual ☐	Blacklight Intensity ____ Bath Mixture ____ Whitelight ____	Magnaflux Developer SKD-S2
Dry Powder	Vis. Liq. Pen. ☑	Residual ☐	Vis. Liq. Pen ☑	Continuous ☐	Long. Insp. ☐	Continuous ☐		Batch # 22A07C
7-HF	Flour Liq. Pen. ☐	Continuous ☐	Flour Liq Pen ☐	AC Current ☐	Trans Insp ☐	AC Current ☐	Equipment / Inspector Information	Dwell Time 10 min
White Contrast	Long. Insp. ☐	AC Current ☐	Long. Insp. ☐	DC Current ☐		DC Current ☐	Equipment Used From Unit # 14	White Light 100+
14-A	Trans. Insp. ☐	DC Current ☐	Trans Insp. ☐	Visible MPI ☐			Cust. Dates) MT ____ PT 11/11/2019	Magnaflux Penetrant. ☑ SKL-WP2
System Effectiveness:	LP-Comparitvo Block ☑	Dry MP-Castrol Strip ☐	Wet MP-Castrol Strip ☐	Profile Gage RSC OK ☑			Level II Inspector: DUSTIN KNIGHT	(Check one) ☐ ZL-60D
							Signature: Dustin Knight	Batch # 22B056
							Signature guarantees final walk thru of job and job site	Dwell Time: 20 min

Job Information

B ____ V ____ D ____ P ____

3rd Party Rep ____

Signature: ____

PDM WJ 012 R DATE 6-6-2022