



# BOTTOM HOLE ASSURANCE, INC.

No. DIR 60722TT-13

Blacklight, Ultrasonic Wall Thickness,  
& Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com  
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC  3RD PARTY  
RIG \_\_\_\_\_  
OCS-G & WELL \_\_\_\_\_

FACILITY / LOCATION TEST TOOLS  
PROJECT IN HOUSE

AUTHORIZED BY BOBBY CHOATE  
P.O. / JOB # 1017510022

INVOICE NO. \_\_\_\_\_  
DATE: 6/7/2022

Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	PIN										BOX														
								Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks				
12850232	X-OVER	1.36	FL	FL	2 1/4	5	5	3 7/8 CAS	-	-	-	-	-	-	-	-	-	-	-	-	NC 38	11/16	4 1/16	-	-	-	-	-	-	4 7/8	-	Acc
13008748	X-OVER	1.64	FL	FL	2 1/4	5	5	NC 38	3 15/16	-	-	-	1/4	4 51/64	-	Rej	PITTED THREADS	3 7/8 CAS	-	-	-	-	-	-	-	-	-	-	-	-	Acc	
12720386	X-OVER	1.48	FL	FL	2 1/4	5	5	3 7/8 CAS	-	-	-	-	-	-	-	Acc		NC 38	5/8	4 1/16	-	-	-	-	-	-	-	4 7/8	-	Acc		