



B O T T O M H O L E A S S U R A N C E , I N C .

Blacklight, Ultrasonic Wall Thickness,
& Liquid Penetrant Inspection

No. IR **61422CWP-1**

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC			3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION CLEAN WELL		AUTHORIZED BY TONY FREDRICK		INVOICE NO.		
RIG			OCS-G & WELL NO.		PROJECT		P.O. NO. / JOB NO.		DATE 6/14/2022	
SERIAL NO.	DESCRIPTION			ACC / REJ.	SERIAL NO.	DESCRIPTION			ACC / REJ.	
1	45135386740107	655264 BLADE			ACC	41				
2	45125750580203	655264 BLADE			ACC	42				
3	45147870820407	655264 BLADE			ACC	43				
4	45116323810107	655264 BLADE			ACC	44				
5	45130779770101	655264 BLADE			ACC	45				
6	45147139430229	655264 BLADE			ACC	46				
7	45148468350222	655264 BLADE			ACC	47				
8	45135386740110	655264 BLADE			ACC	48				
9	45147169000221	654797 BLADE			ACC	49				
10	45147870820104	654797 BLADE			ACC	50				
11	45147753490104	654797 BLADE			ACC	51				
12	45147753490107	654797 BLADE			ACC	52				
13	45149580640113	654797 BLADE			ACC	53				
14	45149580640101	654797 BLADE			ACC	54				
15	45149580640103	654797 BLADE			ACC	55				
16	45138764110111	654797 BLADE			ACC	56				
17	45152723850207	654853 BLADE			ACC	57				
18	45152723850216	654853 BLADE			ACC	58				
19	45152723850211	654853 BLADE			ACC	59				
20	45152723850206	654853 BLADE			ACC	60				
21	45152723850203	654853 BLADE			ACC	61				
22	45152723850204	654853 BLADE			ACC	62				
23	45152723850205	654853 BLADE			ACC	63				
24	45152723850209	654853 BLADE			ACC	64				
25	45103493290316	10162 BLADE			ACC	65				
26	4510263450102	10163 BLADE			ACC	66				
27	45108493290304	10164 BLADE			ACC	67				
28	451072870105	10165 BLADE			ACC	68				
29	3117	10166 BLADE			ACC	69				
30	45107287870113	10167 BLADE			ACC	70				
31	45107287870103	10168 BLADE			ACC	71				
32	45103493290314	10169 BLADE			ACC	72				
33	45137686860117	645800 BLADE			ACC	73				
34	45137686860118	645800 BLADE			ACC	74				
35	45137686860119	645800 BLADE			ACC	75				
36	45137686860120	645800 BLADE			ACC	76				
37	45137686860121	645800 BLADE			ACC	77				
38	45137686860122	645800 BLADE			ACC	78				
39						79				
40						80				

SUMMARY: FULL BODY INSP AS PER BSD-GL-HAL-CWT-201

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input type="checkbox"/>	DC Current <input type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparitive Block Dry MP-Castrol Strip Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>6240</u> Bath Mixture: <u>0.30</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>32</u>
	Qual. Date(s) MT <u>11/30/2021</u> PT _____
Liquid Penetrant Inspection	3rd Party Rep: _____
Whitelight: _____	Signature: _____
Magnaflux Developer: SKD-S2 Magnaflux Penetrant: <input type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D	Level II Inspector: GAELEN ROBIN
Batch # _____ Batch # _____	Signature:
Dwell Time: _____ min Dwell Time: _____ min	Signature guarantees final walk thru of job and job site
Job Information	
B _____ GR V _____ GR D _____ P _____ BP	