



# BOTTOM HOLE ASSURANCE, INC.

No. IR **61722TT-6**

*Blacklight, Ultrasonic Wall Thickness,  
& Liquid Penetrant Inspection*

Email: BHAInc@bottomholeassurance.com  
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.		
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 6/17/2022		
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH	
1	EQ# 11313830	GAUGE CARRIER SG-175						
2	AHY1913516-1	SUB ASSEMBLY - ACC		3 7/8 CAS - ACC	3 7/8 CAS - ACC	2 1/4	5	4.33
3		SAP# 101477670						
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								
36								
37								
38								
39								
40								

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 5

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparitive Block  Dry MP-Castrol Strip  Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>5931</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>13</u>
	Qual. Date(s) MT <u>7/21/2019</u> PT <u>9/21/2021</u>
<b>Liquid Penetrant Inspection</b>	3rd Party Rep: _____
Whitelight: _____	Signature: _____
Magnaflux Developer: SKD-S2 Magnaflux Penetrant: <input type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D	Level II Inspector: RIDGE ALBERT
Batch # _____ Dwell Time: _____ min	Signature:  _____
<b>Job Information</b>	Signature guarantees final walk thru of job and job site
B _____ RA _____ V _____ RA _____ D _____ P _____ RA _____	