



BOTTOM HOLE ASSURANCE, INC.

No. DIR 61822B1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com
109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON
RIG
OCS-G & WELL

3RD PARTY

FACILITY / LOCATION SPERRY DRILLING
PROJECT

AUTHORIZED BY EDDIE FAUCHEUX
P.O. / JOB # 1016910157

INVOICE NO.
DATE: 6/18/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and sub-columns for PIN and BOX.

Remarks: INSPECTED PER D00685901 REV. T - *N1 - 2 TRANSITION AREAS INSPECTED

Bottom section containing inspection details: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information.