



BOTTOM HOLE ASSURANCE, INC.

No. DIR 62022B1

Blacklight, Ultrasonic Wall Thickness, & Liquid Penetrant Inspection

Email: BHAInc@bottomholeassurance.com 109 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964

CUSTOMER HALLIBURTON 3RD PARTY RIG OCS-G & WELL

FACILITY / LOCATION SPERRY DRILLING PROJECT

AUTHORIZED BY EDDIE FAUCHEUX P.O. / JOB # 907749929

INVOICE NO. DATE: 6/20/2022

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and sub-columns for PIN and BOX inspection parameters.

Remarks: INSPECTED PER D00685901 REV. T - \*N1 - 3 FEET OF BLADES INSPECTED

Inspection summary form including sections for Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I., Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, and Job Information.