BOTTOM HOLE ASSURANCE, INC.

No. DIR 20623ST-11

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY DERRICK ROBIN | INVOICE NO.

RIG | PROJECT WOODSIDE | P.O. / JOB # 90892758 | DATE: 2/6/2023

OCS-G & WELL

								PIN										BOX											
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 12628358	9 5/8" EZ WLK																											
G3398313-18	SETTING SLEEVE SAP# 100072799																	INT									Acc	
G3399759-8	TENSION MANDREL SAP# 100072800							INT								Acc		INT									Acc	

Remarks: FULL BODY INSP AS PER MAN-GL-HAL-HCT-900 REV. 5 | Customer Rep Signoff:

Batch # Info.

20-B	20B065
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

Blacklight Inspection

Blacklight Intensity: 3244 Bath Mixture: 0.25 Whitelight: 0.1

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2 (Check one) ☐ ZL-60D
Batch #
Dwell Time: min

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

3rd Party Rep

Job Information

B BT V BT D P BT

Signature: HB7807

Equipment / Inspector Information

Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2019 PT 4/26/2019
Level II Inspector: BRANSON THERIOT
Signature: Branson Theriot

Signature guarantees final walk thru of job and job site

By david.patin@bottomholeassurance.com at 9:07:12 AM, 2/20/2023