BOTTOM HOLE ASSURANCE, INC.

No. DIR 20923ST-1

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY DERRICK ROBIN | INVOICE NO.
RIG | PROJECT SHELL | P.O. / JOB # 908052587 | DATE: 2/9/2023
OCS-G & WELL

								PIN										BOX									
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 12714144	5" FAS FIL																											
3557574-2	TOP ADAPTER SAP# 101336802	0.98	-	-	2 1/4	-	5	INT								Acc		3 7/8 CAS									Acc	
3557329-2	SHEAR CASE SAP# 101236683																	INT INT									Acc Acc	
4604462	SEALING MANDREL SAP# 101336801							INT								Acc												
AHY147361-2	SHEAR SET SLEEVE SAP# 100065587							INT								Acc												
BAS2119	SHEAR PIN COVER SAP# 100065783							*								Acc												
AHY2216553	LOCKING DOG - Acc SAP# 100065588							*								Acc												
BAC1991774-4	SHEAR MANDREL SAP# 100065590																	INT									Acc	
3535456-1	Pressure Housing SAP# 100065594							INT								Acc		INT									Acc	
3542122-1	NIPPLE SAP# 101211418	0.96	-	-	2 1/4	5	-	3 7/8 CAS								Acc		INT (P)									Acc	

Remarks: FULL BODY INSP AS PER MAN-GL-HAL-HCT-900 REV. 5.1 | Customer Rep Signoff:

Batch # Info.
20-B 20B065
Dry Powder
7-HF
White Contrast
14-A

Connection Inspection
Wet Flour. M.P.I. ☑ Dry M.P.I. ☐
Vis. Liq. Pen. ☐ Residual ☐
Flour Liq. Pen. ☐ Continuous ☑
Long. Insp. ☑ AC Current ☐
Trans. Insp. ☑ DC Current ☑

Body Inspection
Wet Flour. M.P.I. ☑ Residual ☐
Vis. Liq. Pen. ☐ Continuous ☑
Flour Liq. Pen. ☐ AC Current ☐
Long. Insp. ☑ DC Current ☑
Trans. Insp. ☑ Visible M.P.I. ☐

Body Dry M.P.I
Dry M.P.I. ☐ Residual ☐
Long. Insp. ☐ Continuous ☐
Trans. Insp. ☐ AC Current ☐
DC Current ☐

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Job Information
B BT V BT D P BT

3rd Party Rep
Signature:

Blacklight Inspection
Blacklight Intensity: 1931 Bath Mixture: 0.25 Whitelight: 0.1

Equipment / Inspector Information
Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2019 PT 4/26/2019
Level II Inspector: BRANSON THERIOT
Signature:
Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection
Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2 (Check one) ☐ ZL-60D
Batch #
Dwell Time: min

By david.patin@bottomholeassurance.com at 9:33:25 AM, 2/20/2023