BOTTOM HOLE ASSURANCE, INC.

No. DIR 20923ST-3

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY DERRICK ROBIN | INVOICE NO.

RIG | PROJECT ENI | P.O. / JOB # 908088949 | DATE: 2/9/2023

OCS-G & WELL

								PIN										BOX									
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 12705080	6 5/8" BP SETTING TOOL																											
B3524119-02	TOP ADAPTER SAP# 100073888	0.43	4 3/8	-	-	-	4 3/4	INT								Acc		2 7/8 8 RD									Acc	
4104894-2	PISTON SAP# 102691224							INT								Acc												
4109551-2	UPPER MANDREL SAP# 102691225							INT INT								Acc Acc												
3528225-3	CASE SAP# 100073889																	INT									Acc	
AC1834713-1	LOWER MANDREL SAP# 102691226							INT								Acc												
BAC21A1634-1	COUPLING SAP# 100073254							INT								Acc												
4713558-1	SETTING SLEEVE SAP# 100073892																	INT									Acc	
4627796-9	LOWER MANDREL SAP#100073893							INT								Acc												

Remarks: FULL BODY INSP AS PER MAN-GL-HAL-HCT-900 REV. 5.1 | Customer Rep Signoff:

Batch # Info.

20-B	20B065
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Job Information

B BT | V BT | D | P BT

3rd Party Rep

Signature: [signature] H2M14

Blacklight Inspection

Blacklight Intensity: 3806 Bath Mixture: 0.25 Whitelight: 0.1

Equipment / Inspector Information

Equipment Used From Unit # 23

Qual. Date(s) MT 4/26/2019 PT 4/26/2019

Level II Inspector: BRANSON THERIOT

Signature: [signature]

Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2

Batch #

Dwell Time: min

White Light:

Magnaflux Penetrant: ☐ SKL-WP2 (Check one) ☐ ZL-60D

Batch #

Dwell Time: min

By david.patin@bottomholeassurance.com at 9:33:28 AM, 2/20/2023