BOTTOM HOLE ASSURANCE, INC.

No. DIR 91823ST-10

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY
RIG
OCS-G & WELL
FACILITY / LOCATION SERVICE TOOLS
PROJECT LLOG
AUTHORIZED BY DERRICK ROBIN
P.O. / JOB # 907596896
INVOICE NO.
DATE: 9/18/2023

								PIN										BOX													
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 12734200	8 1/2" BALL CATHCER																											
AFQ1515941-1	UPPER ADAPTER SAP# 101007520	0.94	-	-	3 15/16	-	8 1/2											6 5/8 FH	5/8	6 13/16					7 23/32		Acc	RE-INSP
AFQ1514551	LOWER ADAPTER SAP# 101007569	0.91	-	-	5	8 1/2	-	6 5/8 FH	4 15/16				9/16	7 13/16		Acc	RE-INSP											

Remarks: CONNECTION INSP AS PER MAN-GL-HAL-HCT-900 REV. 6 (MACHINE SHOP CONNECTION INSPECTION ONLY)

Customer Rep Signoff:

Batch # Info.

20-B	23A106
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☐	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☐
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☐	DC Current	☐
Trans. Insp.	☐	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Job Information

B BT V BT D P BT

3rd Party Rep
Signature: HB71807

Blacklight Inspection

Blacklight Intensity: 4158 Bath Mixture: 0.25 Whitelight: 0.1

Equipment / Inspector Information

Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2019 PT 4/26/2019
Level II Inspector: BRANSON THERIOT
Signature:
Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2
(Check one) ☐ ZL-60D
Batch #
Dwell Time: min

By david.patin@bottomholeassurance.com at 12:15:27 PM, 9/20/2023