# BOTTOM HOLE ASSURANCE, INC.

No. DIR 91823ST-11


*NDE Inspection Services*

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

**Office: (337) 857-8994 Fax: (337) 857-8964**
**Bottomholeassurance.com**


CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY
RIG
OCS-G & WELL
FACILITY / LOCATION SERVICE TOOLS
PROJECT LLOG
AUTHORIZED BY DERRICK ROBIN
P.O. / JOB # 908533674
INVOICE NO.
DATE: 9/18/2023

| | | | | | | | | PIN | | | | | | | | | | BOX | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Serial # | Tool Description | Overall Length | Fishing Neck Length | Tong Space | Pin I.D. | Pin O.D. | Box O.D. | Connection Size | Pin Length | Pin Cylinder Diameter | Pin Nose Diameter | Pin Relief Diameter | Pin Rel. Width Pin Neck Lgth | Bevel Diameter | B S R | OK or Reject | Remarks | Connection Size | Counter Bore Length | Counter Bore Diameter | Bore Back Dia. Float Bore Dia. | Bore Back Lgth Float Bore Lgth | Box Thread Length | Counterbore Wall Thickness | Bevel Diameter | B S R | OK or Reject | Remarks |
| EQ# 12734199 | 8 1/2" BALL CATHCER | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| AFQ1515941-5 | UPPER ADAPTER SAP# 101007520 | 0.96 | - | - | 3 15/16 | - | 8 1/2 | | | | | | | | | | | 6 5/8 FH | 5/8 | 6 13/16 | | | | | 7 23/32 | | Acc | RE-INSP |
| AFQ1514551-2 | LOWER ADAPTER SAP# 101007569 | 0.98 | - | - | 5 | 8 1/2 | - | 6 5/8 FH | 4 15/16 | | | | 9/16 | 7 13/16 | | Acc | RE-INSP | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

**Remarks:** CONNECTION INSP AS PER MAN-GL-HAL-HCT-900 REV. 6 (MACHINE SHOP CONNECTION INSPECTION ONLY)

Customer Rep Signoff:

**Batch # Info.**

| | |
|---|---|
| 20-B | 23A106 |
| Dry Powder | |
| 7-HF | |
| White Contrast | |
| 14-A | |

**Connection Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☑ | Dry M.P.I. | ☐ |
| Vis. Liq. Pen. | ☐ | Residual | ☐ |
| Flour Liq. Pen. | ☐ | Continuous | ☑ |
| Long. Insp. | ☑ | AC Current | ☐ |
| Trans. Insp. | ☑ | DC Current | ☑ |

**Body Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☐ | Residual | ☐ |
| Vis. Liq. Pen. | ☐ | Continuous | ☐ |
| Flour Liq. Pen. | ☐ | AC Current | ☐ |
| Long. Insp. | ☐ | DC Current | ☐ |
| Trans. Insp. | ☐ | Visible M.P.I. | ☐ |

**Body Dry M.P.I**

| | | | |
|---|---|---|---|
| Dry M.P.I. | ☐ | Residual | ☐ |
| Long. Insp. | ☐ | Continuous | ☐ |
| Trans. Insp. | ☐ | AC Current | ☐ |
| | | DC Current | ☐ |

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

**Job Information**

B BT V BT D P BT

3rd Party Rep
Signature: 467807

**Blacklight Inspection**

Blacklight Intensity: 4699 Bath Mixture: 0.25 Whitelight: 0.1

**Equipment / Inspector Information**

Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2019 PT 4/26/2019
Level II Inspector: BRANSON THERIOT
Signature: Branson Theriot
Signature guarantees final walk thru of job and job site

**Liquid Penetrant Inspection**

Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2
(Check one) ☐ ZL-60D
Batch #
Dwell Time: min

*By david.patin@bottomholeassurance.com at 12:15:28 PM, 9/20/2023*