

BOTTOM HOLE ASSURANCE, INC.



NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER Halliburton
RIG
OCS-G & WELL

FACILITY / LOCATION Sperry Drilling
PROJECT

AUTHORIZED BY Kale Veronie
P.O. / JOB # 908078802

INVOICE NO.
DATE: 9/20/2023

Table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, Connection Size, Counter Bore Length, Counter Bore Diameter, Bore Back Dia., Bore Back Lgth, Bore Back Lgth, Box Thread Length, Counterbore Wall Thickness, Bevel Diameter, BSR, OK or Reject, Remarks.

Remarks: Inspection as per D00685901 Rev. U NOTE: All API connections show evidence of Cold Work unless otherwise noted. *N1-TRANSITION AREA INSPECTED-OK

Customer Rep Signoff:

Form sections: Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, Job Information, Signature.