BOTTOM HOLE ASSURANCE, INC.

No. DIR 92123TT-4

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION TEST TOOLS | AUTHORIZED BY BOBBY CHOATE | INVOICE NO.

RIG | PROJECT IN HOUSE | P.O. / JOB # 1017510022 | DATE: 9/21/2023

OCS-G & WELL

								PIN										BOX										
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
12720386	X-OVER	1.43	FL	FL	2 1/4	5	5	3 7/8 CAS								Acc		NC 38	5/8	4 1/16					4 7/8		Acc	

Remarks: FULL BODY INSP. AS PER BSM-GOM-HAL-TT-201 REV.6 | Customer Rep Signoff:

Batch # Info.

20-B 20B065
Dry Powder
7-HF
White Contrast
14-A

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

Blacklight Inspection

Blacklight Intensity: 4010 Bath Mixture: 0.25 Whitelight: 0.1

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2
(Check one) ☐ ZL-60D
Batch #
Dwell Time: min

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

3rd Party Rep

Job Information

B DP V DP D P DP

Signature:

Equipment / Inspector Information

Equipment Used From Unit # 13
Qual. Date(s) MT 3/23/2022 PT 8/23/2022
Level II Inspector: DAVID PATIN
Signature: Signature guarantees final walk thru of job and job site

By david.patin@bottomholeassurance.com at 1:55:21 PM, 9/21/2023