



BOTTOM HOLE ASSURANCE, INC.

No. DIR 112723SB4

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER S.B.E.S. 3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION Shop
PROJECT Halliburton Sperry Drilling

AUTHORIZED BY Aldren Mayea
P.O. / JOB # WO# 325907922

INVOICE NO.
DATE: 11/27/2023

Main inspection data table with columns for Serial #, Tool Description, Overall Length, Fishing Neck Length, Tong Space, Pin I.D., Pin O.D., Box O.D., Connection Size, Pin Length, Pin Cylinder Diameter, Pin Nose Diameter, Pin Relief Diameter, Pin Rel. Width, Pin Neck Lgth, Bevel Diameter, BSR, OK or Reject, Remarks, and various Box dimensions.

Remarks: Dye Pen.Insp.Connection & Body As Per D00685901 Rev: V CW Stamped
Customer Rep Signoff:
Batch # Info, Connection Inspection, Body Inspection, Body Dry M.P.I, Blacklight Inspection, Liquid Penetrant Inspection, Equipment / Inspector Information, Job Information