



BOTTOM HOLE ASSURANCE, INC.

NDE Inspection Services

No. IR 112823TT-2

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.	
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 11/28/2023	
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH
1	EQ# 10254653	8 5/8" - 13 3/8" RTTS SAFETY JOINT					
2	KM-1736007-1	TOP COUPLING - ACC			5 1/4 CAS x INT - ACC	3 3/4	6 1/8 1.35
3		SAP# 100064925					
4	C4079822-2	MANDREL - ACC		INT x INT - ACC			
5		SAP# 100070268					
6	37369	NUT - ACC		INT - ACC			
7		SAP# 100070269					
8	1788183	CASE - ACC			INT x INT - ACC		
9		SAP# 100070251					
10	AHY1812162-3	CONNECTOR - ACC		INT x INT - ACC			
11		SAP# 100070252					
12	AHY124874-4	LOWER ADAPTER - ACC		NC50 - ACC	INT - ACC	3 3/4	6 1/8 1.06
13		SAP# 100070247					
14	KM-1736007-01	CAS TOP ADAPTER-ACC					
15		SAP#100070255					
16	2399793-2	CAS BOTTOM ADAPTER-ACC					
17		SAP#100070248					
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 6

Batch # Info.	Connection Inspection		Body Inspection			Body Dry M.P.I	
20-B 20A106	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>	
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>	
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>	
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>	
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>			

System Effectiveness: LP-Comparative Block Dry MP-Castrol Strip Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>2752</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>13</u> Qual. Date(s) MT <u>2/16/2023</u> PT <u>8/9/2023</u>
Liquid Penetrant Inspection Whitelight: _____ Magnaflux Developer: SKD-S2 Magnaflux Penetrant: (Check one) <input type="checkbox"/> SKL-WP2 <input type="checkbox"/> ZL-60D Batch # _____ Batch # _____ Dwell Time: _____ min Dwell Time: _____ min	3rd Party Rep: _____ Signature: _____ Level II Inspector: BRONZE POIRIER Signature: <u>Bobby Choate</u> <small>Signature guarantees final walk thru of job and job site</small>
Job Information B _____ BP _____ V _____ BP _____ D _____ P _____ BP _____	Customer Rep Signoff: _____



