



# B O T T O M   H O L E   A S S U R A N C E ,   I N C .

NDE Inspection Services

No. IR 41624CWP-1

Email: BHAInc@bottomholeassurance.com  
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994    Fax: (337) 857-8964  
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC			3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION CLEAN WELL		AUTHORIZED BY TONY FREDERICK		INVOICE NO.		
RIG			OCS-G & WELL NO.		PROJECT		S/O		DATE 4/16/2024	
SERIAL NO.	DESCRIPTION			OK / REJ.	SERIAL NO.	DESCRIPTION			OK / REJ.	
1	451009513618	STABILIZER			ACC	1				
2	450867312524	STABILIZER			ACC	2				
3	451270370614	STABILIZER			ACC	3				
4	45155475880102	DRIAN SUB			ACC	4				
5	2237930102	JET SUB			ACC	5				
6	45080019590130	SPLIT HALF			ACC	6				
7	45075280170106	SPLIT HALF			ACC	7				
8	4517982030540	SPLIT HALF			ACC	8				
9	4509290127111	STABILIZER			ACC	9				
10	4512707733614	STABILIZER			ACC	10				
11	451499065731	STABILIZER			ACC	11				
12	451220285114	STABILIZER			ACC	12				
13	451009513613	STABILIZER			ACC	13				
14	45080019590504	STABILIZER			ACC	14				
15	45102169120107	STABILIZER			ACC	15				
16	5884	STABILIZER			ACC	16				
17	45099997580103	STABILIZER			ACC	17				
18	451052096113	CONE			ACC	18				
19	451052096112	CONE			ACC	19				
20	45163968590106	EDUCTOR TUBE			ACC	20				
21	4508823921617	EDUCTOR TUBE			ACC	21				
22	45163968590104	EDUCTOR TUBE			ACC	22				
23	450882392167	EDUCTOR TUBE			ACC	23				
24	451079929733	EDUCTOR TUBE			ACC	24				
25	45138231650106	EDUCTOR TUBE			ACC	25				
26	45138277450104	SPACING			ACC	26				
27	451575534313	SPRING RETAINER			ACC	27				
28	4508021664617	SPRING RETAINER			ACC	28				
29	4513739174921	SPLIT COLLAR			ACC	29				
30	45128348000101	BALL SEAT			ACC	30				
31	45084991670501	SPACING			ACC	31				
32	451018100532	PLUNGER			ACC	32				
33						33				
34						34				
35						35				
36						36				
37						37				
38						38				
39						39				
40						40				

**SUMMARY:**

FULL BODY INSP AS PER BSD-GL-HAL-CWT-201 Rev. 14

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 20B065	Wet Flour. M.P.I. <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input type="checkbox"/>	DC Current <input type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		
System Effectiveness: LP-Comparitive Block <input type="checkbox"/> Dry MP-Castrol Strip <input type="checkbox"/> Wet MP-Castrol Strip <input checked="" type="checkbox"/>						
Blacklight Inspection			Equipment / Inspector Information			
Blacklight Intensity: 5147 Bath Mixture: 0.25 Whitelight: 0.1			Equipment Used From Unit # 32			
			Qual. Date(s) MT 11/30/2021 PT			
Liquid Penetrant Inspection			3rd Party Rep: _____			
Whitelight: _____			Signature: _____			
Magnaflux Developer: SKD-S2		Magnaflux Penetrant: <input type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D		Level II Inspector: GAELEN ROBIN		
Batch # _____		Batch # _____		Signature: <i>Gaelen Robin</i>		
Dwell Time: _____ min		Dwell Time: _____ min		Signature guarantees final walk thru of job and job site		
Job Information			Customer Rep Signoff: _____			
B GR V GR D _____ P CD _____						