BOTTOM HOLE ASSURANCE, INC.

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

No. IR **41724TT-4**

CUSTOMER	3rd PARTY	FACILITY / LOCATION	AUTHORIZED BY	INVOICE NO.
HALLIBURTON ICC	☐	TEST TOOLS	BOBBY CHOATE	

RIG	OCS-G & WELL NO.	PROJECT	P.O. NO. / JOB NO.	DATE
		IN HOUSE	1017510022	4/17/2024

	SERIAL NO.	DESCRIPTION	PIN	BOX	I.D.	O.D.	LENGTH
1	EQ# 12207929	5" BIG JOHN JAR					
2	0004183716-1	TOP COUPLING - ACC	INT (B) - ACC	3 7/8" CAS - ACC	2 1/4	5	0.98
3		SAP# 100066624					
4	664475-1	SPLINED HOUSING - ACC	INT - ACC				
5		SAP# 100066622					
6	AHY2015073-2	IMPACT MANDREL - ACC	INT - ACC	INT - ACC			
7		SAP# 100066605					
8	BBM205347-1	CASE - ACC		INT x INT - ACC			
9		SAP# 100066625					
10	AHY2319236-1	METERING SLEEVE - ACC					
11		SAP# 100066616					
12	3800488-2	METERING NUT - ACC (ALL ACCESSIBLE AREAS)					
13		SAP# 100066608					
14	3929928-3	EQUALIZING PRESSURE PISTON - ACC					
15		SAP# 100066609					
16	BAC21A1677-2	LOWER MANDREL - ACC		INT - ACC			
17		SAP# 100066618					
18	BAC1889749-2	BOTTOM NIPPLE - ACC	3 7/8" CAS x INT - ACC		2 1/4	5	0.63
19		SAP# 100066626					
20	BAC1862315-1	ADJUSTMENT METER CONE - ACC (ALL ACCESSIBLE AREAS)	INT x INT - ACC				
21		SAP# 100066617					
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 6

Batch # Info.	Connection Inspection				Body Inspection				Body Dry M.P.I			
20-B 23K007	Wet Flour. M.P.I.	☑	Dry M.P.I.	☐	Wet Flour. M.P.I.	☑	Residual	☐	Dry M.P.I.	☐	Residual	☐
Dry Powder	Vis. Liq. Pen.	☐	Residual	☐	Vis. Liq. Pen.	☐	Continuous	☑	Long. Insp.	☐	Continuous	☐
7-HF	Flour Liq. Pen.	☐	Continuous	☑	Flour Liq. Pen.	☐	AC Current	☐	Trans. Insp.	☐	AC Current	☐
White Contrast	Long. Insp.	☑	AC Current	☐	Long. Insp.	☑	DC Current	☑			DC Current	☐
14-A	Trans. Insp.	☑	DC Current	☑	Trans. Insp.	☑	Visible M.P.I.	☐				

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑

Blacklight Inspection

Blacklight Intensity: 4240 Bath Mixture: 0.25 Whitelight: 0.1

Liquid Penetrant Inspection

Whitelight: _____

Magnaflux Developer: SKD-S2 Magnaflux Penetrant: (Check one) ☐ SKL-WP2 ☐ ZL-60D

Batch # _____ Batch # _____

Dwell Time: _____ min Dwell Time: _____ min

Job Information

B BP V BP D _____ P BP

Equipment / Inspector Information

Equipment Used From Unit # 13

Qual. Date(s) MT 2/16/2023 PT 8/9/2023

3rd Party Rep: _____

Signature: _____

Level II Inspector: BRONZE POIRIER

Signature: Bronze Poirier

Signature guarantees final walk thru of job and job site

Customer Rep Signoff: CERTIFIED APPROVED

By david.patin@bottomholeassurance.com at 8:45:25 AM, 4/18/2024